




Polybutylene Water Service Lines in the Austin Water Service Area

- Previously Replaced
- To Be Replaced in 5 to 10 year CIP
- Future Replacement Beyond 10 years